

Confidentiality level class 2:

This document intended for a restricted public only (Official Elinchrom agents, partners, suppliers, manufacturers or outsourcers). Any third party dissemination, distribution, copying or use of these documents, without prior permission, is strictly prohibited.

Date: 25.08.2020

Ref. : D.Job

Department: SAV

D-Lite RX ONE & 4 fan (Error E8)

The fan (226.105) for D-Lite RX ONE & 4 units with the serial number "7" in the 3rd position (ex: S2072048701234) and bought before 25 August 2020 could be defective on some units and needs to be repaired by replacing the fan 226.105.

Technical problem


Due to insufficient air flow of the fan, the unit may overheat. In this case the unit will show error E8.

How to recognize the defective fan



How to proceed to get a replacement

Use the "Replacement Program" of the D-Lite RX ONE & 4 available in our Distributors Center > Warranty Claims > Replacement Programms to obtain the requested quantity of fan 226.105 you need.



elinchrom Elinchrom Distributors Center

Home Online Contact Details Promotional Resources Webshop Technical Center **Warranty Claims** Logout

Home New Case Drafts Open Cases Shipment Process To Be Closed Archives **Replacement Programs**

OSRAM Halogen Modelling Lamps 23005 (2017-01-01 - 2021-01-01)

D-Lite RX ONE & 4

D-Lite RX fan (Error E8) (2020-08-01 - 2022-01-01)

ELB 1200

Flash Heads ELB 1200 - Tilt bracket defective (2017-11-01 - 2020-11-01)

Snaplux Speedring Q-Mount - 26549

Snaplux Speedring Q-Mount - 26549 (2020-01-01 - 2022-01-01)

Zoom Heads

Improvement for 240.077 Cable Sleeve for Zoom Head (2014-01-01 - 2021-01-01)

Copyright © 2020 ELINCHROM SA. All rights reserved. Conception: Cybor SA