

Confidentiality level class 2:

This document intended for a restricted public only (Official Elinchrom agents, partners, suppliers, manufacturers or outsourcers). Any third party dissemination, distribution, copying or use of these documents, without prior permission, is strictly prohibited.

Date: 28.05.2015

Ref :

Department: R&D

Mains fuse is blowing

In some rare cases, the ELC Pro HD units might be affected by blowing the mains fuse.

This problem appears when there is a short circuit in the T200 component on the Power board SMPS 270.540.ADJ version 2C and older.

ELC Pro HD series

The following ELC Series might be show this problem :

Serial numbers ELC Pro HD 500 : **1402061300101** to **1502061306224**

Serial numbers ELC Pro HD 1000 : **1402061600101** to **1502061603953**

How to solve the problem

Replace the mains fuse and the Power board SMPS 270.540.ADJ

