

Confidentiality level class 2:
 This document intended for a restricted public only (Official Elinchrom agents, partners, suppliers, manufacturers or outsourcers). Any third party dissemination, distribution, copying or use of these documents, without prior permission, is strictly prohibited.

Date: 06.01.2016

Ref. : D.Job


Department: SAV

Batteries warranty

According to our warranty agreement I-00029, the batteries warranty criteria are defined in the warranty document 73031. (available in the Technical Center)


Top-plate fuse holders

Due to a plastic manufacturing default on some old series, the plastic top-plate fuse holders can break off on Li-Ion batterie boxes 19295.



How to proceed to get a replacement

If you find this issue, please fill and send a warranty request form to obtain the replacement free of charge of the Li-Ion Battery top plate RQ/ELB 400 **260.020**.

260.020	Li-Ion Battery top plate RQ/ELB 400	
----------------	-------------------------------------	---