

Confidentiality level class 2:

This document intended for a restricted public only (Official Elinchrom agents, partners, suppliers, manufacturers or outsourcers). Any third party dissemination, distribution, copying or use of these documents, without prior permission, is strictly prohibited.

Date: 07.06.2017

Ref. : Mladen S.

Department: R&amp;D

## PROBLEM

According to the User Manual (73014) a long press of *state of charge* button shows you if the battery is in failure mode. After an upgrade of battery's firmware in 2014 a small mistake was done. This option was disabled.

## SOLUTION

Therefore the ELB400's firmware is updated (version 1.8). Simply select *Li-ion LED update* in the service menu, and the *failure mode* check is again enabled.

Select “Li-Ion LED update” in the service menu.  
(available since ELB400 firmware version 1.8)

