

Confidentiality level class 2:

This document intended for a restricted public only (Official Elinchrom agents, partners, suppliers, manufacturers or outsourcers). Any third party dissemination, distribution, copying or use of these documents, without prior permission, is strictly prohibited.

Date: 04.11.2015

Ref. : D.Agier

Department: R&D

## BRX/D-Lite Keyboard Adhesive Foil

Some Keyboard adhesive foils on BRX or D-Lite series could come off or the bubble buttons could be perforate after a hard use. Because the panel foil is a security insulation barrier between the user and the inside dangerous voltages, any damaged panel foil has to be replaced immediately by the Elinchrom distributor.



If you find a unit with these symptoms or if a customer complains about a damaged keyboard adhesive foil, you have to replace as soon as possible for safety reasons this foil by a new one.

Example:



## What part to replace

If the keyboard panel foil is damaged, replace by a new one.

Units	Spare part	Spare part number	Description
BX-Ri / BRX		227.015	Keyboard Adhesive Foil BXRi/BRX
D-Lite it/RX/One		226.015	Keyboard Adhesive Foil D-Lite

Before paste the new keyboard adhesive foil, take care to clean the front panel housing correctly with isopropyl alcohol.

## How to proceed to get a replacement

Please fill in the warranty form to obtain the replacement free of charge of the requested spare parts.